




# Part # 11132401

61-64 Buick Full Size, 63-65 Riviera Front HQ Shockwave, OEM Control Arms



### **Recommended Tools**





# 1000 Series Bellow, 2.75" Stud/Trunnion 2.9" Shock Installation Instructions

THE CONTROL ARMS NEED TO BE REINFORCED IN THE AREA THAT THE TRUNNION BOLTS TO.

| Page 3-4   | Included comp<br>Shockwave Inst | tallation | wave & Sh | ock Adjustment                  |      |
|--|---------------------------------|-----------|-----------|---------------------------------|------|
| ShockWave Dim<br>Mount to Moun<br>Compressed:<br>Ride Height:<br>Extended: | t:                              |           |           |                                 |      |
| THE DELRIN BALL RI<br>GO THROUGH. THIS                                     | -                               |           |           | vww.ridetech.co<br>812-482-2932 | om - |






# Major Components .....In the box

### THE CONTROL ARMS NEED TO BE REINFORCED IN THE AREA THAT THE TRUNNION BOLTS TO.

| ltem<br># | Part #       | Description<br>2.9" Stroke HQ Series Shock                              |   |
|-----------|--------------|---|---|
| 1         | 982-10-802   |   |   |
| 2         | 90009989     | 2.75" Stud Top (preassembled on Shock) - Includes Adjuster Knob & Screw |   |
| 3         | 24090199     | 1000 Series 6.5" Double Convoluted AirSpring                            |   |
| 4         | 234-00-153   | AirSpring Locking Ring (preassembled on shock)                          |   |
| 5         | 99055000     | Locking Ring Set Screw (preassembled on shock)                          |   |
| 6         | 90001659     | Buick Trunnion (preassembled in shock)                                  |   |
| 7         | 90002313     | 2.75" Aluminum Stud Top Base  | 2 |
| 8         | 90001904     | Bottom Delrin Ball  | 2 |
| 9         | 90001903     | Top Delrin Ball   | 2 |
| 10        | 90001902     | Delrin Ball Aluminum Top Cap  | 2 |
| 11        | 99562003     | 9/16"-18 Thin Nylok Nut   | 2 |
| 12        | 210-35-120-0 | Adjuster Knob - (90009989 assembly)                                     | 2 |
| 13        | 90009969     | #4-40 X 1/4" SS, 18-8 Pan Head Torx Cap - (90009989 assembly)           | 2 |
| 14        | 90001634     | Trunnion Locking Rings (preassembled in shock)                          | 4 |
| 15        | 90009936     | Trunnion/Bushing Shims (preassembled in shock)                          | 4 |
| 16        | 70009554     | Poly Bushing (preassembled in shock)                                    | 4 |
|           | 70012161     | 2.75" Stud Top Metering Rod (preassembled in stud top)                  | 2 |
|           | 99311002     | 5/16" X 1 1/4" Hex Bolt   | 4 |
|           | 99312003     | 5/16"-18 Nylok Nut  | 4 |
|           | 99313002     | 5/16" SAE Flat Washer   | 8 |



THE DELRIN BALL REQUIRES A 3/4" HOLE FOR THE FLANGE TO GO THROUGH. THIS CAN BE DRILLED WITH A UNIBIT.





## **ShockWave Installation**







**1.** Drill the OEM shock hole out to 3/4". This can be done with a Unibit.


**2.** Some trimming must also be done on the outside of the frame pocket to allow clearance for the Shockwave.

**3.** The upper plate of lower control arm must also be trimmed for Shockwave clearance.





## ShockWave Installation



**Note:** The airline must also be routed at this time. It can be ran through the subframe toward the rear of the vehicle.

**4.** The air fitting location can be rotated by twisting the bellow assembly separate of the shock. Place the Shockwave into the coil spring pocket with the stud sticking through the OEM shock hole. See assembly **Diagram 4**. OEM Shock hole **must** be drilled out to <sup>3</sup>/<sub>4</sub>"

- **1.** Stud top aluminum base
- 2. Delrin ball lower half
- 3. Delrin ball upper half
- 4. Aluminum cap
- 5. 9/16" SAE Nylok jam nut
- 6. Threaded stud (screwed onto shock shaft)
- 7. Rebound adjusting knob
- 8. Screw

**TIGHTENING THE TOP 9/16"-18 NUT:** SNUG THE NUT DOWN AGAINST THE TOP CAP. YOU NEED TO BE ABLE TO ARTICULATE THE SHOCK BY HAND.

**5.** Raise the lower arm up to the Shockwave and bolt them together using the 5/16" x 1 1/4" Bolts, Washers, & Nylok Nuts supplied with the ShockWaves. Torque to 17 ftlbs.

**6.** Raise the lower control arm to full compression and double-check to make sure the Shockwave does not rub on anything at anytime. Allowing the Shockwave to rub on anything will cause failure and is not a warrantable situation.

**7.** The best ride quality will occur around 50-60% suspension travel; depending on vehicle weight this typically occurs around 90-100 psi.





### **Notes and Care of your Shockwaves**

**NOTES:** 

WARNING: ATTEMPTING TO REMOVE THE AIR FITTING WILL DAMAGE IT AND VOID THE WARRANTY.

**TIGHTENING THE TOP 9/16"-18 NUT:** SNUG THE NUT DOWN AGAINST THE TOP CAP. YOU NEED TO BE ABLE TO ARTICULATE THE SHOCK BY HAND. WE TORQUE THE NUT TO 80 INLBS USING A 7/8" CROWS FOOT WRENCH ON A TORQUE WRENCH.

You can clock the airfitting location on the ShockWave by turning the AirSpring assembly of the shock. Make sure the fitting doesn't contact the frame.

When cutting the airline, use a razor blade. The cut needs to be a clean cut and square for the airline to seal properly.

The Locking ring on the shock is NOT adjustable. These rings are set at the factory to optimize the AirSpring stroke with the shock stroke.

# The care and feeding of your new ShockWaves

1. Although the ShockWave has an internal bumpstop, **DO NOT DRIVE THE VEHICLE DEFLATED RESTING ON THIS BUMPSTOP. DAMAGE WILL RESULT**. The internal bumpstop will be damaged, the shock bushings will be damaged, and the vehicle shock mounting points may be damaged to the point of failure. This is a non warrantable situation.

2. Do not drive the vehicle overinflated or "topped out". Over a period of time the shock valving will be damaged, possibly to the point of failure. This is a non warrantable situation! If you need to raise your vehicle higher that the ShockWave allows, you will need a longer unit.

3. The ShockWave is designed to give a great ride quality and to raise and lower the vehicle. **IT IS NOT MADE TO HOP OR JUMP!** If you want to hop or jump, hydraulics are a better choice. This abuse will result in bent piston rods, broken shock mounts, and destroyed bushings. This is a non warrantable situation.

4. Do not let the ShockWave bellows rub on anything. Failure will result. This is a non warrantable situation.

5. The ShockWave product has been field tested on numerous vehicles as well as subjected to many different stress tests to ensure that there are no leakage or durability problems. Failures have been nearly nonexistent unless abused as described above. If the Shockwave units are installed properly and are not abused, they will last many, many years. ShockWave units that are returned with broken mounts, bent piston rods, destroyed bumpstops or bushings, or abrasions on the bellows will not be warrantied.





# Shock Adjustment

# Shock Adjustment 101- Single Adjustable

#### **Rebound Adjustment:**

How to adjust your new shocks.

The rebound adjustment knob is located on the top of the shock absorber protruding from the eyelet. You must first begin at the ZERO setting, then set the shock to a medium setting of 12.





-Begin with the shocks adjusted to the ZERO rebound position (full stiff). Do this by rotating the rebound adjuster knob clockwise until it stops.

-Now turn the rebound adjuster knob counter clock wise 12 clicks. This sets the shock at 12. (settings 21-24 are typically too soft for street use).

Take the vehicle for a test drive.





-if you are satisfied with the ride quality, do not do anything, you are set!

-if the ride quality is too soft increase the damping effect by rotating the rebound knob clock wise 3 clicks.

#### Take the vehicle for another test drive.



-if the vehicle is too soft increase the damping effect by rotating the rebound knob clock wise 3 additional clicks.

-If the vehicle is too stiff rotate the rebound adjustment knob counter clock wise 2 clicks and you are set!

Take the vehicle for another test drive and repeat the above steps until the ride quality is satisfactory.

#### Note:

One end of the vehicle will likely reach the desired setting before the other end. If this happens stop adjusting the satisfied end and keep adjusting the unsatisfied end until the overall ride quality is satisfactory.